

ข้อสรุป

loop triangle measure method			werner method
	3m	6m	
Rab	37.5	40.7	
Rbc	44.8	65	
Rca	43.6	61.5	
Ra	18.15	18.6	23-24
Rb	19.35	22.1	
Rc	25.45	42.9	

$$Ra = (Rab + Rca - Rbc) / 2$$

$$Rb = (Rab + Rbc - Rca) / 2$$

$$Rc = (Rca + Rbc - Rab) / 2$$